

Mappa, Inc.

1956 Richardson Highway
North Pole, AK 99705
(907) 488-1266

Special Inspection Daily Report

Client: Cornerstone

Project: FTW405

Test Date: 10/27/25

Test Time: 2p

Inspector: John Trush

Contact: Jake / Calvin

Type of Inspection: Reinforcing steel

Time Charged to Project: Start Time 130

End Time 230

Total Hours Charged RT 2 OT

Inspections performed and locations

Location	Inspection Performed
<u>Operation Storage Foundation Walls A-C/1-4</u>	<u>Inspection of reinforcing steel was performed at listed location. Reinforcing bars placed were the correct sizes, shapes, type, in clean condition and placed in forms free of debris. Forms were constructed from approved materials and shored securely to hold shape. Inspected reinforcing steel appeared installed in accordance with approved contract documents for spacing, clearance and lap splice. Rebar 58°F Prior to Placement. Please reference DWG 03 Operation Storage Foundation plan and wall section.</u>

Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

<u>NONE</u>

Changes to approved plans authorized by engineer or architect of record (include paperwork)

<u>NONE</u>

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: 

Printed Name: John R Trush CGT