

# Mappa, Inc.

1956 Richardson Highway  
North Pole, AK 99705  
(907) 488-1266

## Special Inspection Daily Report

Client: Ekwtua Project: EIE Fuel & Lab Facility

Test Date: 5/13 Test Time: 1030 Inspector: MMM

Contact: \_\_\_\_\_ Type of Inspection: Proof Rolling/Plating

Time Charged to Project: Start Time 1015 End Time 1200 Total Hours Charged RT 2 OT \_\_\_\_\_

### Inspections performed and locations

Location	Inspection Performed
<u>Bldg Foundation</u>	<u>Observed proof rolling operations performed by sub-contractor Great-Northwest @ listed location. During operations observed no pumping, deflection, or soft areas. Proof was performed by (4) Husqvarna plate compactors.</u>


### Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	<u>None</u>

### Changes to approved plans authorized by engineer or architect of record (include paperwork)

	<u>None</u>

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: 

Printed Name: Markus Mack