

Mappa, Inc.

1956 Richardson Highway
North Pole, AK 99705
(907) 488-1266

Special Inspection Daily Report

Client: Alcan Builders Project: EIE430
Test Date: 6/19/25 Test Time: _____ Inspector: John Trush
Contact: Bobby Type of Inspection: Reinforcing steel
Time Charged to Project: Start Time 12 End Time 1 Total Hours Charged RT 2 OT _____

Inspections performed and locations

Location	Inspection Performed
<u>Fire Pump Room addition: Utility Pit Slab</u>	<u>Inspection of Reinforcing steel at listed location. Reinforcing bars placed were the correct sizes, shapes, type, in clean condition and placed in forms free of debris. Forms are made of approved materials and shored to hold shape. Inspected Reinforcing bars appear installed in accordance with approved Contract documents for spacing, clearances and lap splice. Please reference Drawing Number 01 Utility Pit section, Fire Pump Room Foundation Plan</u>

Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	<u>NONE</u>

Changes to approved plans authorized by engineer or architect of record (include paperwork)

	<u>NONE</u>

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: 

Printed Name: John R. Trush CET