

Mappa, Inc.

1956 Richardson Highway  
North Pole, AK 99705  
(907) 488-1266

Special Inspection Daily Report

Client: Alcan Builders Project: EIE430

Test Date: 08/02/25 Test Time: 12p Inspector: John Trush

Contact: Bobby Type of Inspection: Pcc placement

Time Charged to Project: Start Time 12 End Time 2301 Total Hours Charged RT \_\_\_\_\_ OT 3  
concrete 50 minutes late

Inspections performed and locations

Location	Inspection Performed
MH-2 Foundation Walls	Observed the placement of 11.5 cu yds of 6034 1 SL-25 concrete at listed locations.
MH-2 Hydrant walls	Concrete was placed by pump and consolidated by electric powered internal vibrator. Concrete
Continuous Footing 1.6 l. x D.3-B.6	was placed and consolidated in accordance with approved contract documents.
Spread Footings C.4/1.6, D.1/1.6	Tested 6034 1 SL-25 concrete for air content, Slump, unit wt. and temp. 9 Strength Specimens were cast with test.

Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	<u>NONE</u>

Changes to approved plans authorized by engineer or architect of record (include paperwork)

	<u>NONE</u>

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: [Signature] Printed Name: John R. Trush CBT