

Mappa, Inc.

1956 Richardson Highway
North Pole, AK 99705
(907) 488-1266

Special Inspection Daily Report

Client: Alcan Bldrs

Project: EIE 430

Test Date: 5/6

Test Time: 745

Inspector: Markus Mack

Contact: _____

Type of Inspection: Rebar

Time Charged to Project: Start Time 645

End Time 815

Total Hours Charged RT 2 OT _____

Inspections performed and locations

Location	Inspection Performed
MH-1, 2, 3 Roof Risers. DWG No. 04 MH-1 Roof Riser Plan	All Bar @ listed locations meets project specifications for type, sizing, spacing, laps, counts & clearances. All Bar is clean & free from deleterious materials.
	Forms appear sturdy & well built to proper specifications. All forms are clean & free of debris

Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	<u>None</u>

Changes to approved plans authorized by engineer or architect of record (include paperwork)

	<u>None</u>

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: _____

Printed Name: Markus Mack