

Mappa, Inc.

1956 Richardson Highway
North Pole, AK 99705
(907) 488-1266

Special Inspection Daily Report

Client: Heritage Project: EIE B9039 Koyuk LSG

Test Date: 5/7 Test Time: 730 Inspector: MJM

Contact: _____ Type of Inspection: Rebar

Time Charged to Project: Start Time 630 End Time 800 Total Hours Charged RT 1 OT .5

Inspections performed and locations

Location	Inspection Performed
<u>LSG Slab on Grade</u>	<u>All Bar @ listed location meets project requirements for Type, Laps, Sizing, spacing & Clearances. All Bar is clean & free of deleterious materials. Forms are seemingly sturdy, free of debris & well built to proper specifications.</u>

Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	<u>None</u>

Changes to approved plans authorized by engineer or architect of record (include paperwork)

	<u>None</u>

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature:  Printed Name: Markus Mack