

# Mappa, Inc.

1956 Richardson Highway  
North Pole, AK 99705  
(907) 488-1266

## Special Inspection Daily Report

Client: Red Point Project: FTW BLDG 3484  
Test Date: 5/16/26 Test Time: \_\_\_\_\_ Inspector: John Trush  
Contact: Kyle Type of Inspection: Pcc placement  
Time Charged to Project: Start Time 1230 End Time 2 Total Hours Charged RT \_\_\_\_\_ OT 2

### Inspections performed and locations

Location	Inspection Performed
<u>BLDG 3484 D</u> <u>(7) Pipe supports</u> <u>(10) Bollards</u>	<u>Observed the placement of 10 cu yds of 253445A-1 concrete at listed locations. Concrete was placed by chute and consolidated by internal vibrator (battery powered). Concrete was placed and consolidated in accordance with approved contract documents.</u>
	<u>Tested 253445A-1 concrete for temperature, Slump, air content, and unit wt. 6 strength specimens were cast with test. No water was added on site.</u>

Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	<u>NONE</u>

Changes to approved plans authorized by engineer or architect of record (include paperwork)

	<u>NONE</u>

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: [Signature] Printed Name: John R. Trush CET