

# Mappa, Inc.

1956 Richardson Highway  
North Pole, AK 99705  
(907) 488-1266

## Special Inspection Daily Report

Client: Eklutna Project: FTW 475

Test Date: 8/25 Test Time: 1200 Inspector: msm

Contact: \_\_\_\_\_ Type of Inspection: Civil QC

Time Charged to Project: Start Time 1130 End Time 130 Total Hours Charged RT 2 OT \_\_\_\_\_

### Inspections performed and locations

Location	Inspection Performed
<u>Canopy Pilaster &amp; Vault Brick</u>	<u>Observed Civil Activities performed by sub-contractor Fullford Electric. (1) Kobuto SVL 75-3 skid steer, (1) John Deere 35D mini-ex, (2) Supra Plate Compactors, (2) Husqvarna Plate Compactors placed, graded &amp; compacted Import material.</u>


### Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	<u>None</u>

### Changes to approved plans authorized by engineer or architect of record (include paperwork)

	<u>None</u>

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature:  Printed Name: Markus Mack