

Mappa, Inc.

1956 Richardson Highway
North Pole, AK 99705
(907) 488-1266

Special Inspection Daily Report

Client: EKLUTNA

Project: FTW475

Test Date: 6/11/26

Test Time: 11A

Inspector: John Trush

Contact: Ken

Type of Inspection: Reinforcing steel

Time Charged to Project: Start Time 1030

End Time 12

Total Hours Charged RT 2 OT

Inspections performed and locations

Location	Inspection Performed
<u>(3) Guard Booth Pads</u>	<u>Inspection of Reinforcing steel was performed at listed locations.</u>
	<u>Reinforcing bars inspected were the correct size, shapes, type, in clean condition and placed in curbs forms free of debris.</u>
	<u>Inspected Reinforcement appeared installed in accordance with approved contract documents for spacing and clearance.</u>
	<u>Please reference sheet S-501 E8 Guard Guard booth Pad-Plan and E-15 Guard booth Pad-section</u>


Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	<u>NONE</u>

Changes to approved plans authorized by engineer or architect of record (include paperwork)

	<u>NONE</u>

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: 

Printed Name: John R. Trush CET