

956 Richardson Highway
North Pole AK 99705
907/488-1266

Special Inspection Daily Report

Client: Ames 1 Project: Deficient VCHQ WTP WRST
Job Date: 8/14 Job Time: 9:30 Inspector: W. Harding
Contract: CHAD Type of Inspection: Rebar
Time Charged to Project: Start: 2:30AM End: 10:00AM Total Time: 7.5 8 5

Inspections performed and locations

Location	Inspection Performed
THKND Edge @ Overhead Dwg No. 1	All Bar @ listed location meets project requirements for type, size, spacing, laps, counts, and clearances. #5 HK DWLS are in place and properly secured. Bar placed in existing slab is properly installed with epoxy. All Bar is clean and free of deleterious materials. Forms appear well built and sturdy according to project specifications. All Forms are clean and free of debris.

Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	None

Changes to approved plans authorized by engineer or architect of record (include paperwork)

	None

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: Wayne Harding Printed Name: Wayne Harding