

Mappa, Inc.

1956 Richardson Highway
North Pole, AK 99705
(907) 488-1266

Special Inspection Daily Report

Client: H.C. Contractor

Project: Veteran Cemetery

Test Date: 8/17/20

Test Time: 8

Inspector: John Trush

Contact: SAM

Type of Inspection: Reinforcing steel

Time Charged to Project: Start Time

7

End Time 9 30

Total Hours Charged RT 3 OT

Inspections performed and locations

Location	Inspection Performed
Columbarium #3	Inspection of reinforcing steel was performed at listed locations.
Footing to 3'-6"	
Memorial wall	Inspected Reinforcing Bars are the correct sizes, shapes, type, in clean condition and placed in forms free of debris. Forms are constructed of approved materials and securely shored to maintain shape. Inspected reinforcement appeared to be installed in accordance with approved contract documents for spacing, clearance and bar count. Please reference Drawing 02 columbarium at end, columbarium section and memorial wall section.
Footing to 5'-3 1/8"	

Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	<u>NONE</u>

Changes to approved plans authorized by engineer or architect of record (include paperwork)

	<u>NONE</u>

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: [Signature]

Printed Name: John P. Trush CET