Mappa, Inc.

1956 Richardson Highway
North Pole, AK 99705
(907) 488-1266

Special Inspection Daily Report

Client: Aleut Project: Denali C-Camp

Test Date: 6/27/26 Test Time: 9am Inspector: MSM

Contact: _____ Type of Inspection: Rebar

Time Charged to Project: Start Time 630 End Time 1100 Total Hours Charged RT 4 OT .5

Inspections performed and locations

Location	Inspection Performed
Footing (Fox Block) Walls	All Bar @ listed locations meets project
Dwg No. 02	requirements for Type, laps, sizing, spacing,
Details: Wall	counts & clearances. All Bar is clean &
Section 01, Wall	free of deliterious materials.
Section 02	Forms (Fox Block) appears sturdy & well built to
Interior Footings	proper specifications Forms are clean &
x9 F1, x2 F2,	free of debris.
x2 F3	
Dwg No. 02	
Detail: Footing	
Shedule	

Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	None

Changes to approved plans authorized by engineer or architect of record (include paperwork)

	None

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: _____ Printed Name: Markus Mack