

Mappa, Inc.

1956 Richardson Highway
North Pole, AK 99705
(907) 488-1266

Special Inspection Daily Report

Client: Paving Products

Project: PPI New Shop

Test Date: 7/30/26

Test Time: 1100

Inspector: mylm

Contact: _____

Type of Inspection: Rebar

Time Charged to Project: Start Time 1030 End Time 1200 Total Hours Charged RT 2 OT _____

Inspections performed and locations

Location	Inspection Performed
Shop Slab w/ thick Edge - Dwg No. 01 Fndtn Reinforcing Plan, Thick Edge Section, Pilaster Section, Pilaster Schedule, Dwg No. SSO1 Details: 1-Pilasters 2-Typ Conc Pedestal & Footing Schedule 3-Grid & Anchor Rods.	All Bar @ listed locations meets project requirements for type, laps, sizing, spacing, counts & clearances. All Bar is clean & free of deleterious materials. Anchor bolts are in place as measured by contractor. Forms appear sturdy & well built to proper specifications. Forms are clean & free of debris. Blockouts are in place.

Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

4-Hairpin Details, None	
6-Grid & Ftg	

Changes to approved plans authorized by engineer or architect of record (include paperwork)

None	

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: _____

Printed Name: Markus Mark