

Mappa, Inc.

1956 Richardson Highway
North Pole, AK 99705
(907) 488-1266

Special Inspection Daily Report

Client: CLDS Project: LDSTemple

Test Date: 06/08/26 Test Time: 1PM Inspector: John Trush

Contact: Jaden Type of Inspection: Reinforcing Steel

Time Charged to Project: Start Time 1230 End Time 2 Total Hours Charged RT 2 OT

Inspections performed and locations

Location	Inspection Performed
Temple Piers @ F/2, F.4/2, G/2, H/2, F/2.5, F/3, F/4, G/2.5, G/3, G/4, H/3, H/3.5, H/4, I/3, I/6, J/3, J/4, J/6, K/3, K/4, K/6, J.6/6, L/6 L/6.5, L/7, L/8, K/7, K/7.5, K/8, J.6/6, J.6/8, J/6.5, J/7, J/8, K/10, K/11, J/10, J/11, H/10, H/11, H/12, G/10, G/11, G/12	Inspection of Clearance of Bars to forms for 3/4" tolerance was performed at listed locations. Reinforcement bars had been previously inspected for spacing and count. Reinforcing Bars are in side forms constructed of approved material and are securely shored to hold shape. Inspected Reinforcing bars appear installed in accordance with approved contract documents for clearance.

Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

F/10, F/11, F/12, D.5/3	NONE
D.5/4, D.5/6, D/7, D/7.5, D/8, D.5/8, D.5/10, D.5/11, C.7/4, C.7/10	

C.5/6, C/3, C/4, C/6, C/7, C/8, C/10, C/11

Changes to approved plans authorized by engineer or architect of record (include paperwork)

B/6, B/7, B/8, A.5/8	NONE

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: [Signature] Printed Name: John R. Trush CET