

Special Inspection Daily Report

Client: Westland Project: LDS ANCILLARY
 Test Date: 5/7/26 Test Time: _____ Inspector: John Trush
 Contact: Taken Type of Inspection: Pile Cap to pile welds
 Time Charged to Project: Start Time 7A End Time 11 Total Hours Charged RT 4 OT _____

Inspections performed and locations

Location	Inspection Performed
Cap to Pile: P1#511, P3#542, P1/512, P2/539, P2/541, P2/514, P2/515, P2/540 P2/538, P1/513, P2/537, P2/534, P2/517, P2/516, P1/510, P1/509, P2/556, P2/518, P2/533 P2/536, P2/535, P2/555 P1/508, P2/507, P2/519 P2/532, P2/530, P1/543	Welding inspection was performed on A36 20" x 20" x 3/4" Cap to A252-3 pile at listed piles. Piles have been prepped with disc grinder to remove rust, slag and mill scale. 5/16" fillet welds all the way around were inspected visually and with feeler gauge. Inspected welds appeared installed in accordance with approved WPS and AWS P1.1 visual acceptance criteria. Please reference Detail 1 Page A-530-01
Items requiring correction, correction of previously listed items and/or previously listed uncorrected items	
P1/550, P1/551, P1/506, P2/505, P2/520, P2/531, P2/528, P2/529, P2/544, P2/549, P2/542, 552, P2/553, P2/548, P2/545, P2/526, P2/527 P2/521, P2/504, P2/503, P2/522, P2/525	
Changes to approved plans authorized by engineer or architect of record (include paperwork)	
P1/502, P2/523, P1/524, NONE P2/546, P2/547, P1/554	

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: _____ Printed Name: John R. Trush CET