

Diappa, Inc.

1956 Richardson Highway
North Pole, AK 99705
(907) 488-1266

Special Inspection Daily Report

Client: Cornerstone Project: FTW 405

Test Date: 5/28/26 Test Time: _____ Inspector: John Trush

Contact: Calvin Type of Inspection: Bottom of Excavation

Time Charged to Project: Start Time see EPOXY End Time _____ Total Hours Charged RT _____ OT _____

Inspections performed and locations

Location	Inspection Performed
<u>Fighting Position #9</u>	<u>Inspection of Bottom of Excavation was performed at listed locations.</u>
<u>FP #8/9 Parking Pad</u>	<u>Visual inspection of Bottom of Excavation was silty sand w/ Gravel, No deleterious materials or Organics were present</u>
	<u>Recommendations:</u>
	<u>Proof roll subgrade with self propelled vibratory Roller, 4 Passes prior to installation of Fabric and Gravel Back Fill.</u>

Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	<u>NONE</u>

Changes to approved plans authorized by engineer or architect of record (include paperwork)

	<u>NONE</u>

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: [Signature] Printed Name: John R. Trush CET