

Mappa, Inc.

1956 Richardson Highway
North Pole, AK 99705
(907) 488-1266

Special Inspection Daily Report

Client: Corner stone Project: FTW 405
Test Date: 6/22/26 Test Time: _____ Inspector: John Trush
Contact: Jack Type of Inspection: Pcc Placement
Time Charged to Project: Start Time 11 End Time 1230 Total Hours Charged RT 2 OT _____

Inspections performed and locations

Location	Inspection Performed
(1) <u>SIT @ Lane 1-10</u> <u>Wall</u>	<u>Observed the placement of 1 cu yd of 25 3445a-s1</u> <u>Concrete at listed location. Concrete was placed</u> <u>by chute and consolidated by Battery powered</u> <u>Internal vibrator. Concrete was placed and</u> <u>Consolidated in accordance with approved contract</u> <u>documents.</u>
	<u>Tested 25 3445 @ s1 concrete for air content,</u> <u>Slump, temp and unit wt. 9 strength specimens</u> <u>were cast with test.</u>
	<u>No Water was added on site.</u>

Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	<u>NONE</u>

Changes to approved plans authorized by engineer or architect of record (include paperwork)

	<u>NONE</u>

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: [Signature] Printed Name: John R Trush CET