

1956 Richardson Highway
North Pole, AK 99705
(907) 488-1266

Special Inspection Daily Report

Client: Cornerstone

Project: FTW 405

Test Date: 7/20/26

Test Time: 430

Inspector: msm

Contact: _____

Type of Inspection: Rebar

Time Charged to Project: Start Time 415 End Time 615 Total Hours Charged RT .75 OT 1.75

Inspections performed and locations

Location	Inspection Performed
Latrine Stoops E&S	All Bar @ listed locations meets project requirements for type, sizing, spacing, laps, counts & clearances. All Bar is clean & free of deleterious materials. Contractor used plans for latrine stoops for N & S Classroom stoops.
Classroom Stoops N&S	
Dwg No. 06	
Latrine Bldg	
Foundation Plan	
Firing Position Walls	Forms appear clean, sturdy, & well built to proper specifications.
1 & 2	
Firing Position Slabs	
5, 6, 7, & 8	
Dwg No. 01	

Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	<u>None</u>

Changes to approved plans authorized by engineer or architect of record (include paperwork)

	<u>None</u>

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: _____

Printed Name: Markus Mack