

Mappa, Inc.

1956 Richardson Highway
North Pole, AK 99705
(907) 488-1266

Special Inspection Daily Report

Client: Cornerstone

Project: FTW 405

Test Date: 7/30/26

Test Time: 300

Inspector: MM

Contact: _____

Type of Inspection: Rebar

Time Charged to Project: Start Time 230 End Time 330 Total Hours Charged RT 2 OT _____

Inspections performed and locations

Location	Inspection Performed
<u>Firing Positions</u>	<u>All Bar @ listed location meets project requirements for type, sizing, spacing, laps, counts & clearances. All Bar is clean & free of deleterious materials.</u>
<u>586 Walls</u>	
<u>Dwg No. 01</u>	
<u>Firing Position</u>	
<u>Wall Section</u>	<u>Forms appear sturdy & well built to proper specifications. Forms are clean & free of debris</u>

Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	<u>None</u>

Changes to approved plans authorized by engineer or architect of record (include paperwork)

	<u>None</u>

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: _____

Printed Name: Markus Mack