

Mappa, Inc.

1956 Richardson Highway
North Pole, AK 99705
(907) 488-1266

Special Inspection Daily Report

Client: Cornerstone Project: FTW 405
Test Date: 9/6 Test Time: 900 Inspector: MSM
Contact: _____ Type of Inspection: Bottom Rebar
Time Charged to Project: Start Time 900 End Time 930 Total Hours Charged RT 2 OT _____

Inspections performed and locations

Location	Inspection Performed
<u>Classroom Cont Footing</u>	<u>All Bar @ listed location meets project requirements for Type, Laps, Sizing Spacing, Counts & Clearances. All Bar is clean & free of deleterious materials.</u>
<u>Drawing No: 05</u>	
<u>Detail: Range</u>	
<u>Classroom</u>	
<u>Foundation Plan</u>	<u>Forms appear sturdy & well built to proper specifications. Forms are clean & free of debris.</u>

Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	<u>None</u>

Changes to approved plans authorized by engineer or architect of record (include paperwork)

	<u>None</u>

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: _____

Printed Name: Markus Mark