

# Mappa, Inc.

1956 Richardson Highway  
North Pole, AK 99705  
(907) 488-1266

Special Inspection Daily Report

Client: Cornerstone Project: FTW 405

Test Date: 9/6 Test Time: 130 Inspector: MMM

Contact: \_\_\_\_\_ Type of Inspection: Placement

Time Charged to Project: Start Time See Field Sheet End Time --- Total Hours Charged RT --- OT ---

Inspections performed and locations

Location	Inspection Performed
<u>Schoolhouse Cont Footing</u>	<u>Observed placement of 9.5 cu yds of 6034 IS1-25 4500 psi concrete, placed as per specifications @ listed location. Consolidation was achieved by use of internal vibrator. All concrete was placed by chute. Test taken in middle 3rd of truck. Test results were w/in project requirements. See Field Sheet for results.</u>

Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	<u>None</u>

Changes to approved plans authorized by engineer or architect of record (include paperwork)

	<u>None</u>

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature:  Printed Name: Markus Mack