

# Mappa, Inc.

1956 Richardson Highway  
North Pole, AK 99705  
(907) 488-1266

## Special Inspection Daily Report

Client: Cornerstone Project: FTW 405

Test Date: 10/11 Test Time: 530 Inspector: MSM

Contact: \_\_\_\_\_ Type of Inspection: Placement

Time Charged to Project: Start Time 500 End Time 615 Total Hours Charged RT 2 OT \_\_\_\_\_

### Inspections performed and locations

Location	Inspection Performed
<del>Mass Hall</del> Slab on grade Classroom	Observed placement of 22 cu yds of 55341NA-23 4000 psi concrete @ listed location placed as per specifications. All concrete placed by <del>pour</del> <sup>chute</sup> pump, placed with Consolidation achieved by use of Internal Vibrator.
	Test Taken w/in middle of 1st truck. Results were w/in project requirements. See field sheet for results.

### Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	<u>None</u>

### Changes to approved plans authorized by engineer or architect of record (include paperwork)

	<u>None</u>

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: 

Printed Name: Markus Mack

# Mappa, Inc.

1956 Richardson Highway  
North Pole, AK 99705  
(907) 488-1266

## Special Inspection Daily Report

Client: Cornerstone Project: FTW 405  
Test Date: 10/11 Test Time: 1pm Inspector: MM  
Contact: \_\_\_\_\_ Type of Inspection: Placement  
Time Charged to Project: Start Time 1230 End Time 300 Total Hours Charged RT 2.5 OT \_\_\_\_\_

### Inspections performed and locations

Location	Inspection Performed
<u>Amme Dump Pilasters Tower Stem Walls</u>	<u>Observed placement of 13 cu yds of 6034 Is 1-25 concrete placed as per specifications @ listed locations. All locations placed by pump. Consolidation achieved by use of internal vibrator. Test taken w/in middle 3rd of 1st truck. Results were w/in project Requirements. See Field Sheet for results.</u>

### Items requiring correction, correction of previously listed items and/or previously listed uncorrected items

	<u>None</u>

### Changes to approved plans authorized by engineer or architect of record (include paperwork)

	<u>None</u>

To the best of my knowledge, work inspected was in accordance with the approved plans and specifications

Signature: \_\_\_\_\_

Printed Name: Markus Mack